

M. Landscape and Visual Audit Photos

 <p>2017/07/31</p>	 <p>2017/07/31</p>
<p>Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)</p>	<p>Photo 2: The wetland areas are being established, with the ponds are being seasonally filled with rain water. (CM2)</p>
 <p>2017/07/31</p>	
<p>Photo 3: Advance screen planting of noise barrier has been undertaken (CM6)</p>	