

Appendix M. Landscape and Visual Audit Photos

	
Photo 1: The Construction works have been screened by hoarding / noise barriers. (CM2)	Photo 2: The wetland areas are being established, with the ponds are being seasonally filled with rain water.(CM2)
	
Photo 3: Advance screen planting of noise barrier has been undertaken. (CM6)	